

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-275-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date 11-12-07, 19

MISCELLANEOUS FIELD NOTES

F6 Von Guernard SLD, AMS, NRM

1421 NO Flow

Entire box has been flipped upside down and N_2 tank valve has blown off!

Apparently tie down cords for box broke and box is sitting upside down in streambed

orifice line severed and we are removing batteries, connoflow, and accubar sensor in order to flip and re-place the box