U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-275-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date Dec 2, 2005, 19

MISCELLANEOUS FIELD NOTES

Lawson Creek @ B3 SLH, JCK

site visit to do levels, check for flow

→ NO FLOW!

└ but BF team has seen it "raging" w/in last week

N_2 tank: 2000 psi

line: 10 psi

orifice still iced in but bolt clear for levels

*6@ 11:32

1 17.84

2 -99999

3 0.0000

+ 13.45

No. _____ of _____ sheets

Form 9-276
(July 1967)

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey
WATER RESOURCES DIVISION

STATION NUMBER

LEVEL NOTES

STREAM Larson @ B3
LOCALITY
PARTY JCK & SLH DATE 12/2/5, 19

STATION	B. S.	HT. INST.	F. S.	ELEVATION	REMARKS
RM1	6.360	16.360		10.000	bolt 6' downstream of box
RP1			8.590	7.77	top of cedar
orifice			10.155	6.205	
PZF			10.340	6.020	
TP			10.565	5.795	
	9.470	15.265			
PZI			9.245	6.020	
orifice			9.060	6.205	
RP1			7.495	7.770	
RM1			5.270	9.995	

NO. ____ OF ____ SHEETS ____ COMP. BY ____ CHK. BY ____